



Steps to accurate measurement





Packing Height measure



- - *The best measuring time is in the morning at the same time.
 *Please take off your hat before measurement.
 - 1. Stand up straight with foot inside footprint mark.
 - 2. Check patient back slightly touches ruler.

 - 3. Pull plate down to patient head.
 - 4. Record measurements.

